

Diagnosis: Land Rover - JATCO AUTOMATIC GEARBOX

Vehicle: **GV02 OGG** Model: *not identified yet*

Trouble Codes
010110
110011
101000
0001



Show Erased

Description	Status
P0748 - Pressure Control Solenoid "A"	Not Present
P0753 - A Shift Solenoid	Not Present
P0758 - B Shift Solenoid	Not Present
P0763 - C Shift Solenoid	Not Present
P1715 - Intermediate Speed Sensor	Not Present
P1748 - Brake timing solenoid	Not Present
P1785 - Clutch Timing Solenoid	Not Present
P1786 - Reduction Timing Solenoid	Not Present

Diagnostic Trouble Code Information

Code: **P0743**

Description: **P0743 - Torque Converter Clutch Circuit**

Detail: **Electrical Failure**

Status: **Not Present**



Return

Diagnosis: Land Rover - JATCO AUTOMATIC GEARBOX

Vehicle: **GV02 OGG** Model: *not identified yet*

Trouble Codes
010110
110011
101000
0001



Show Erased

Description	Status
P0758 - B Shift Solenoid	Not Present
P0763 - C Shift Solenoid	Not Present
P1715 - Intermediate Speed Sensor	Not Present
P1748 - Brake timing solenoid	Not Present
P1785 - Clutch Timing Solenoid	Not Present
P1786 - Reduction Timing Solenoid	Not Present
P1787 - Brake timing solenoid	Not Present

Diagnostic Trouble Code Information

Code: **P1785**

Description: **P1785 - Clutch Timing Solenoid**

Detail: **Short Circuit**

Status: **Not Present**



Return